

### **JASON**

Pella Mid-Atlantic, Inc. 12100 Baltimore Avenue, Suite 1 Beltsville, MD 20705 301-957-7070 MHIC136537 VA 2705170176

Installation Date: 6/30/21

## **Fella**Windows and Doors

Customer Name:

Address:	Order#:717HANN58
	Crew: Rigo 1
Phone Day:	_ Delivery:
Night:	Install Pick-up: 7-10 am
Cell:	Custom Stain or Paint:
7	1
C.O.D. Payment Schedule: elivery Payment (due before installation):  ompletion Payment:	alled Jesun.
elivery Payment (due before installation):	The state of the s
ompletion Payment:	ame caro on the
If paying by check – text picture & customer nar	me to payments@pellamidatlantic.com
If paying by card - call into (301) 957-7008	
(Visa, Master Card, Discover & American Express)	
Finance Bloom size below to suth size that finance	atana and a same
Finance: Please sign below to authorize that finance	cing can be ran:
Customer	_
Complete the following after walk through with crev	w leader.
List Any Deficiencies:	
Mary mark	
Item#	Specific Problem
5 Dorme	PS Meed to be
(208:00	
Capter	
4	
E	
žį.	×
Customer Comments:	
	2
	[2-27, 14
Customer Signature:	Date: Date:
Crew Leader Signature:	Date: 6/30/2/
olow Loader Oighature.	Date.



## Renovation Recordkeeping Chacklist

Name of Firm: Estate	Cens mee Line			
Date and Location of Renovation: # 137	121			
Job Name:(b) (6)(b) (	6)(b) (6)			
Order Number:	ANNSX			
Brief Description of Renovation: Ing	1) 4 PFil wondows			
Name of Assigned Renovator:				
Name(s) of Trained Worker(s), if us				
Name of Dust-Sampling Technicia				
Copies of renovator and dust-sampling technicia	n qualifications (training certificates, certifications) on file			
Certified renovator provided training to workers				
Posting warning signs	Setting up plastic containment barriers			
Maintaining containment	Avoiding the spread of dust to adjacent areas			
Waste handling	Post-renovation cleaning			
Copy of the "Test Kit Documentation Form" provided to the property owner/occupant				
Warning signs posted at entrance to work area				
Work area contained to prevent spread of dust an	d debris:			
All objects in the work area removed or covered (interiors)	Doors in and within 20 feet of the work area closed and sealed (exteriors)			
HVAC ducts in the work area closed and covered (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust			
Windows in the work area closed (interiors)				
Windows in and within 20 feet of the work area closed (exteriors)	Floors in the work area covered with taped-down plastic (interiors)  Ground covered by plastic extending 10 feet from the work area; plastic			
Doors in the work area closed and sealed (interiors)	anchored to building and weighed down by heavy objects (exteriors)  If necessary, vertical containment installed to prevent migration of dust and debris to adjacent property (exteriors)			
Waste contained on-site and while being transporte				
Work site properly cleaned after renovation:				
	eting misted, folded dirty side inward, and taped for removal			
★ Work area surfaces and objects cleaned using	HEPA vacuum and/or wet cloths or mops (interiors)			
Certified renovator performed post-renovation clear	Ding verification (1)			
T leged LAC	Roll of Play Hel.   Baby Wipe			
If dust clearance testing was performed instead	d, attach a copy of report.			
I certify under penalty of law that the above informat				
Name (b) (6)(b)	6/30/2/			
	Date			





			*		
-1.	Name		,		
-	- 1 (b) (	6	In Time	Sign-out Time	
		\$	7:30 AT	100. PM	]
		-	7 30 AM	LOU PM	$\exists$
**				,	
				1	1
F			7		
E					*
F					

# United States Environmental Protection Agency This is to certify that



All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires May 18, 2020

NAT-26214-2

Certification #

January 28, 2015

Issued On



Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch